



15.00 12.5

Assembly instructions for Bolted NFR

- Attach top angle to uprights using 5/16 flat washer, 5/16 lock
- washer and 5/16 16 heavy hex nut.

 Attach the 2 floor angles using 3/8-16 x 1 hex head cap screw, 3/8 flat washer, 3/8 - 16 heavy hex nut.
- Steel





## AAA: HEIGHT ## OB4 = 84" or 7'-0" overall height ## O90 = 90" or 7'-6" overall height ## D90 = 90" or 7'-6" overall height ## BB: UPRIGHT SPACING ## O0 = Welded EIA Wide (1-1/4" - 1/2") ## O1 = Welded EIA Universal 5/8" - 5/8" - 1/2") ## O2 = Welded WECO(1" Pattern) ## 50 = Bolted EIA Wide (1-1/4" - 1/2") ## D1 = Bolted EIA Universal 5/8" - 5/8" - 1/2")	NFR	AAA	BB	XX
52 = Bolted WECO(1" Pattern)	AAA: HEIGHT 084 = 84" or 7'-0" overall height		00 = Welded EIA 01 = Welded EIA 02 = Welded WE 50 = Bolted EIA 51 = Bolted EIA	30 = TELCO GRAY 47 = RAVEN BLACK T SPACING Wide (1-1/4" - 1/2") Universal 5/8" - 5/8" - 1/2") CO(1" Pattern) Wide (1-1/4" - 1/2") Universal 5/8" - 5/8" - 1/2")